



JAB

 Order JAB-D-L-T-SR-d-A **M** :S45C

ØD		ØH	T	SR	Ød	A
16	$\begin{smallmatrix} 0 \\ -0.011 \end{smallmatrix}$	40	20	0 11 12 13 16 19 21	2 2.5 3 3.5 4 4.5 5	1° 2° 3°
			25			
			30			
20	$\begin{smallmatrix} 0 \\ -0.013 \end{smallmatrix}$		20			
			25			
			30			

@ ¥/P											
L40	L50	L60	L70	L80	L90	L100	L110	L120	L130	L140	L150

