




JAA

 Order JAA-D-L-T-SR-d-A **M** :S45C

ØD	ØH	ØP	T	SR	Ød	A
12	0		10			
16	-0.009	35	15	0 11 12 13	2 2.5 3 3.5	1° 2° 3°
20	0		20			
16	-0.011	50	10	0 11 12 13 16	4 4.5 5	
20	0		15			
25	-0.013		20			

@ ¥ /P											
L40	L50	L60	L70	L80	L90	L100	L110	L120	L130	L140	L150

