

RRCPNZ
 RRCPLZ

1. Effective to prevent resin powders from being mixed in the products. When the resin with a high transparency etc. are used, it will generate chipping powder when the resin of undercut part is releasing from the mold.
2. The runner groove direction can be changed from the PL side using a hexagonal wrench as well as conventional products.
3. Please use a ball plunger for positioning.



Installation Diagram:

