


R19




Order R19-D-H



:S45C

| D   | H  | @ ¥/P |
|-----|----|-------|
| 40  | 6  |       |
| 60  | 8  |       |
| 80  |    |       |
| 90  |    |       |
| 100 |    |       |
| 110 |    |       |
| 120 |    |       |
| 125 |    |       |
| 130 | 12 |       |
| 140 |    |       |
| 150 |    |       |
| 160 |    |       |
| 175 |    |       |
| 200 |    |       |
| 250 |    |       |



Order R19-D-H



:S45C

| D   | H  | S   | @ ¥/P |
|-----|----|-----|-------|
| 40  | 9  | 3   |       |
| 60  | 11 | 5   |       |
| 80  | 13 | 3   |       |
| 90  | 15 | 5   |       |
|     | 17 | 7   |       |
|     | 19 |     |       |
| 110 |    |     |       |
| 120 | 21 | 8.5 |       |
| 125 |    |     |       |
| 150 |    |     |       |

