

180~200°C (5S)260



- Precision alloy casting, economie and durable.
- 2. Its application is flexible and easy by the Shoulder screws and Spring plunger.
- 3. To protect the mold base and the bolts, do not forget to open the ZZ73A tool safety devices when mold moving. Otherwise, the front hook or the screws would break first.

| Size | | | (kg) | @ V /D |
|------|------|----|--------|--------|
| Α | В | T | weight | @¥/P |
| 1030 | 1230 | 5 | 15.2 | |
| | | 6 | 18.2 | |
| | | 8 | 24.3 | |
| | | 10 | 30.4 | |
| | | 12 | 36.5 | |

