




ZZ12



Order ZZ12-d1-L1 **M** :SUJ2 **H** :58-62HRC

d1	L1	L	L2	d3	d4	S2	f	Hmax	@ ¥/P
12	40 56	24	2.1	22	26	18	6	50 82	
18	45 56 71	34	3	30	35	23			
30	56 75 95	54	4.8	46	52	33			

