



R20






☐Order R20-D-H	M :S45C			
D	н	h	d2	@¥/P
60 80	8 12	4	90	





☐Order R20-D-H	M :S45C				
D	н	h	d2	s	@¥/P
60	11 13	7 9	00	3 5	
80	15 17	7 9	90	3	





Order R20-D-H	M :S45C			
D	н	h	d2	@¥/P
100 110	12	4	90	
120	12			
125 140 150				
160 175				
160 175 200 250				