
DTZ





Order	DTZ-Ød-L	M	:SCM43	5 🛚	:33-38HR(	0					
Ød		ØD		Т		w		L1	F	м	@¥/P
Size	Tolerance	Size	Tolerance	Size	Tolerance	**	-			M	@ +//F
10		16	0 -0.43	8	0 -0.36	6	16 21	18	22 27	M 6	
13	0 -0.15	18		10		8	14 19 24	24	30 35 40	M 8	
16		24	0 -0.52			10	15 20 30	26	35 40	M10	
20	0 -0.2	28		14	0 -0.43	14	20 30 35	30	45 50 55	M12	
25	-0.2	33	0 -0.62	18	-0.43	17	31 41	38	60 65	M16	